

- INSTRUCTIONS**
1. Original and/or subsequent record used to evaluate the corner position.
 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
 3. Description of monument and accessories set to perpetuate the corner position.
 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography like, position of accessories, etc.
 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner S36 S31


36 N T. 35 N R. 27 W 26 P.M.M.

Lincoln County

RECORD: Original G.L.O. survey - 1894

B.L.M. Remonumentation:

At the corner point, set an iron post, 30" long, 2½" diam., 26" in the ground, in concrete, with brass cap mkd.,



From which:

A fir, 18" diam., bears N.77½° E. 32 lks. dist., mkd. T36N R26W S6 BT.
 A dead fir, 12" diam., bears S.79½° E. 55 lks. dist., mkd. T35N R26W S6 BT.
 A larch, 34" diam., bears S. 6½° W. 52 lks. dist., mkd. X 1 HES 781 BT.
 A dead fir, 16" diam., bears S.66° W. 46 lks. dist., mkd. X 1 Hes 781 BT.

The new bearing trees:

A fir, 6" diam., bears S.12½° E. 71 lks., mkd. T35N R26W S6 BT.
 A larch, 7" diam., bears S. 61 W. 41 lks. dist., mkd. T35N R27W S1 BT.
 A fir, 10" diam., bears N.3 W. 80 lks. dist., mkd. T36N R27W S36 BT.


Bury the original stone alongside and raise a mound of stone, 3' base, 2' high, S. of the iron post

FOUND: A 3½" diam. B.L.M. brass cap approx. 1 " above grnd., mkd. as shown, adjacent to mnd. of stone.

From which:

A fir, 18" diam., bears N03° N. 53.1' dist., scribing visible.
 A fir, 20" diam., bears N.79° E. 21.5' dist., healed face.
 A larch, 34" diam., bears S.07° W. 34.6' dist., scribing visible.
 A fir, 7" diam., bears S.15° E. 47.2' dist., healed face.
 A larch, 8" diam. bears S61° W. 27.4' dist., healed face.

NOTE: This corner is also corner #1 of H.E.S. #781 which was surveyed May 22, 1917, and was reclaimed by the Forest Service Nov. 28, 1930. No reference to this H.E.S. corner was made in the B.L.M. remonumentation notes.




CERTIFICATION	
I, <u>James W. Reed</u> , certify the information shown herein is true and correct.	
<u>James W. Reed</u> Signature Ground Party Chief	
I, <u>Thomas C. Hill</u> , certify that this corner record correctly represents work performed by me or under my direction in compliance with the "Corner Reestablishment Act" (10-28-1935, ch. 54, M.D.A.)	
<u>Thomas C. Hill</u> Signature of Surveyor & Seal	
Date: <u>3/15/83</u>	Reg. No. <u>5612 S</u>
Employer: <u>U.S.F.S.</u>	

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the June 16 day of 1983. was noted on the cross-index plat and is assigned page No. 2241, in book No. _____.

Shirley B. Siegel by Betty L. Concess
County Official deputy

Cross Index No. A-1 T. 35 R. 26 P.M.M.



* - corner this sheet

[REDACTED]