



## ERTIFIED LAND CORNER RECORDATION

(REFERENCE FSH 5681.65)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

1/4 CORNER COMMON TO SECTION 8 AND 9, T.35N., R.26W., P.M.M. LINCOLN, COUNTY, MONTANA

Found 1 1/2" IRON PIPE WITH IRON CAP AND BLAZED TREES, WITH 5" x 2 1/2" x 12 STONE NO MARKINGS. RECORD-LIME STONE 17X6X5" , IN THE GROUND FOR 1/4 SECTION CORNER MARKED 1/4 on West face from which a tamarack 36" in diam., bears S. 88° E., 33 links distance marked 1/4 S. BT A FIR 14" IN DIAM., .BEARS N. 30° W., 4 LINKS DISTANCE MARKED 1/4 S. BT

> DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

> > Date of work: AUG. 8, 1973

was noted on the cross-index plat and is

35

THE MONUMENT AND BEARING TREES WERE NOT CHANGED

D 15" PINE WITH BLAZE

60-D NAIL

"15" PINE WITH BLAZE

Office of Clerk and Recorder, County of Since In

This "corner record" was filed for record on the .......

-60-D NAIL

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

S-8 5-9 15" PINE BLAZE 32 60-D NAIL	I'M PIPE & STONE	N.
Surveyor's Seal	I, ROBERT E HAHN	DIAGRAM OF CORNER:
Surveyor's Sear	certify that the information shown herein is true and	
	Robert E. Lahn	<del>T</del> '
	Signature of Ground Party Chief	. 5-8 🕻 5-9
	I, JAMES L. HAHN	
	certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.	T35N R26W
	Signature of Surveyor	Corner recorded on the sheet
	Signature of Surveyor	
	2795 S	
•	Registration Number	

day of Lin

- ,

.