(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No previous record of monumentation on file.

## DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 5/5/80....

Set a  $2\frac{1}{2}$ " X 30" aluminum pipe 24" in the ground, with a raised mound of stone around the pipe. Cap marked as shown: From which:

A larch, 7" dia., bears S72°E, 11.7 FT., marked CW 1/16 S3 BT. A larch, 7" dia., bears N 09°E, 13.7 FT., marked x BT. Location poster attached to a douglas fir, 14" dia., bears N54°W, 12.3 FT.

C W 1/16 C S3 S6128 1980

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

SO°27'08"E 2665.12'

Surveyor's Seal



I, Anthony J. Bachman certify that the information shown herein is true and correct.


Signature of Ground Party Chief

Thomas C. Hill

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:



= Corner recorded on the sheet

56/2-5 Registration Number

Office of Clerk and Recorder, County of	<i>)</i>
	0 -1-1
This "corner record" was filed for record on the day of .	Delates 19.80, was noted on the cross-index plat and is
	County Official Del,
assigned page No, in book No	Cleaner S. Vaughan by Detty Dell,
	Cross Index No. 14-C T. 35N R. 26W Mer.

