INSTRUCTIONS

- Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch examp topography ties, position of accessories, etc.

 5. Certification must be almost and accessories.
- Certification must be signed and sealed by Registered Land Surveyor in State of Mo
 Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner HES 331-1

R 26W

Lincoln P.M.M.

County

RECORD: 1960 BLM: Cor. No. 1 of Homestead Entry Survey No. 331, monumented with a slate stone, $24 \times 10 \times 8$ ins., firmly set and marked 1 HES 331 on the NW. face, and witnessed by the remains of the original bearing trees.

A fir 18 ins. diam., bears S12½E., 34 lks. dist., mkd. X HES 331 BT. (record S12-35-00W, 34 lks.) A stump, 16 ins. diam., bears N57½W, 26 lks. dist. (record: N57-35-00W., 26 lks.)

Set an iron post, 30 ins. long, 2½ ins. diam., 26 ins. in the ground, in concrete, with brass cap mkd.

> T36N R26W 1|5 13

from which new bearing trees:


A larch 11 ins. diam., bears N81 3/4W, 71 lks. dist., mkd. 1 HES 331 BT.


Bury the original stone alongside and raise a mound of stone, 3 ft. base, 2 ft. high, NW of the iron post.

FOUND: A 34" BLM brass cap approx. 3" above ground adjacent to mound of stone.

FROM WHICH:

A 24" fir bears S10E, 22.2 ft., scribing healed face. A 14" larch bears N86W, 47.2 ft., scribing healed face.





•		•
14 LARCH		
NO6°W		1
W 47.21 9 v	•	•
برا ق		j
4		
1	·	
J24"FIR	•	N
SKETCH OF CORNER		

	AMES W. REED
certify th	e information shown herein is true and correct.
	ms WRaul
	Signature Ground Party Chief
	Signature Ground Party Chief
0	Signature Ground Party Chief
I,	
I,	at this Corner Record correctly represents work performe
by me o	at this Corner Record correctly represents work performer under by direction in compliance with the "Corner to the control of
by me o	at this Corner Record correctly represents work performe
by me o	at this Corner Record correctly represents work performer under by direction in compliance with the "Corner to the control of

CERTIFICATION

Signature of Surveyor & Seal Date: 1-27-82 Reg. No. 56/2-5

Office of Clerk and Recorder, County of Lincoln . This "corner 16/2 record" was filed for record on the ______ was noted on the cross-index plat and is assigned page No. . <u>1603</u> book No. Vaughn by

County Official acputy.

- corner this sheet

Sec.

T. 36N R. 26W PMM