## CERTIFIED LAND CORNER RECORDATION

.. DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Not Previously Set .

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

9-15-75

Date of work:....

Mae Water

Cross Index No. 9-6 T. 36 N. R. 26W Mer.

Set USFS brass cap at the proper location for the SW 1/16 Section 20, from which:

A 24" Ponderosa Pine bears N6°W 95.79 feet. A 28" Ponderosa Pine bears N 77°E 8.35 feet.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 181.

Surveyor's Seal	S. R. Smith	DIAGRAM OF CORNER:
	certify that the information shown herein is true and correct.	N.
	Signature of Ground Party Chief	SW YIL COR.  SECTION 20  T 36N R 26V
	I,Dean K. Marquardt certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.	1975 PMM. 2989 E.
	Dean X Miargrandt • Signature of Surveyor	= Corner recorded on the sheet
	ES2989 Registration Number	