## CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Original Record: Post 4' long x 4" square from which

Spruce 4" bears N. 63° E. 44 lks.

Spruce 6" bears 5.24° E. 11 lks

Fir 6" bears 5.370 W. 72 lks.

Tamarack, bears N. 26° W. 18 lks

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: May ... 1975

County Official Walton Dignty

Cross Index No. V-5 T. 36N RZGW Mer.

Set brass cap 12.55 Fence Post by double proportion

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 152

	· · ·	DIAGRAM OF CORNER:
Surveyor's Seal	I,	736002564
	certify that the information shown herein is true and correct.	N.
		30 29
	Signature of Ground Party Chief	————
		31   32
	I, Dean K. Marquardt	
	certify that I have carefully performed or reviewed the	
	work done on the diagrammed corner as reported on this	· ·
	recordation form and approve the same.	
	Wa exp	= Corner recorded on the she
	Dlan X Magnarde	<u></u>
	Signature of Surveyor	•
	ES2989	
	Registration Number	
· · · · · · · · · · · · · · · · · · ·		
	9	