CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

G.L.O. Record: Set a Post marked "1/4S" on North face from which:

A 14" Fir bears N 1°15' W 59 links

A 9" Tamarack bears S 34°30' E 15 links

Found: A squared post (not G.L.O.) on old fenceline, original G.L.O. post with scribing still visible lying on ground at base. An old Fir stump badly rotted, bears N 5°W 40.3', an old Tamarack stump with destroyed face bears S 18° E 9.6'. Set brass cap at base of post described above.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Rotted 14" Fir Stump Date of work: Nov. 1975

IN 20° Fir

Fence line (new N-S fenceline is

20' West). Rotted original G.L.O.

Post lying alongside, Scribing visible.

Set 13/4" x 30" Iron pipe with Brass Cap.

Old 10" Tamarack Stump,

Face destroyed

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey Number 152

			w	
Surveyor's Seal	s.	R. Smith	DIAGRAM OF CORNER:	
burveyor's Bear	correct.	tion shown herein is true and	N. 7 36 N	
	S & Smith Signature of	Ground Party Chief	S29. 1/4 S32	
	certify that I have caref work done on the diagram recordation form and app	quardt ully performed or reviewed the named corner as reported on this rove the same. Maynard re of Surveyor	R 26 W — = Corner recorded on the sheet	
		ES2989 Registration Number		
Office of Clerk and Recorder, Co.	unty of Lineals			
This "corner record" was filed for	or record on the 28th day of	January 1976, Wa Eleannes, O	s noted on the cross-index plat and is	-
ORM 125 - 41605		Cross Index No. V-7	nty/Official T. 36N R. 26W Mer.	