INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of monument and accessories set to perpetuate the corner position.
 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking. topography ties, position of accessories, etc.
- topography treat, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

36 N., 26 W., _ T. ______R. _____P.M.M. s 1/4 of s32 Lincoln Corner_ County 1893 G.L.O. record by A. Jaqueth et al: Tree corner and two bearing trees. 1959 BLM record: The 1/4 sec. cor.of secs. 5 and 32, on the S. bdy. of the Tp., monumented with a fir tree. 17 ins. diam., mkd. with an overgrown blaze, and witnessed by the remains of the original bearing trees. Not remonumented. From which the remains of the original bearing trees: A fir, 19 ins. diam., bears \$25 W. 16 lks.(10.56 ft.) dist., mkd. 1/4 S BT.(Record)

A dead fir, 16 ins. diam., bears N45 W. 40 lks.(26.40 ft.) dist., mkd. 1/4 S BT.(Record) The new bearing trees: A fir, 6 ins. diam., bears S15 $1/4^{\circ}$ E, 31 lks.(20.46 ft.) dist., mkd. 1/4 S5 BT. A fir, 9 ins. diam., bears N47 W. 71 lks.(46.86 ft.) dist., mkd. 1/4 S32 BT. II. Found a dead fir, 18 ins. diam., mkd. with an overgrown blaze on the NE face. From which: A root crown, bears N40°W, 26.6 ft. dist.

A fir, 10 ins. diam., bears S15°E, 20.6 ft. dist., healed face.

A fallen tree, 19 ins. diam., bears S26°W, 10.5 ft. dist., visible scribing. A fir, 15 ins. diam., bears N47°W, 46.8 ft. dist., healed face. III. Established one new bearing tree: A fir, 9 ins. diam., bears N73 W, 49.0 ft. dist., mkd. 1/4 s32 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. galvanized steel guard post with Land Survey Marker decal, South, 3 ft. Magnetic Declination: 20° East



Kevin A. Todd Ronald A. Pearson certify that this Corner Record correctly represents work performed my direction in compliance (70-22-101, ct-seq., M.S.A.) 10/1/92 Reg. No. _ 9008 LS Employer: U.S. FOREST SERVICE **SKETCH OF CORNER** Lincoln __ . This "corner Office of Clerk and Recorder, County of _ record" was filed for record on ____ was noted on the cross-index plat and is assigned page No. . book No. _ County Official corner this sheet Cross Index No. .