
CERTIFIED CORNER RECORDATION

| Corner | SW 1/16 | Sec. | 25 | T. | 36N | R. | 27W | P.M., MT | Lincoln | County |
|--------|---------|------|----|----|-----|----|-----|----------|---------|--------|

- 1975 Certified Corner Recordation by Dean K. Marquardt: Set a U.S.F.S. brass cap, at I. the proper location for SW 1/16, sec. 25. Established two bearing trees. *In reference to Certificate of Survey No. 181A.
- Found a B.L.M. brass cap, protruding 4 ins. above the ground, firmly set, mkd. as shown. II. A 1 1/2 in. diam. steel pipe with tie wire wrapped around it, bears N., 2 ins. from the cap.



from which:

A larch, 18 ins. diam., bears North, 6.9 ft. dist. (1975-record-N03°W, 6.3 ft.) A larch, 16 ins. diam., bears S53°E, 24.3 ft. dist. (1975-record-S49°E, 24.36 ft.)

Both trees have healed blazes, no visible scribe and had State bearing tree signs.

III. Set two steel galvanized guard posts and reblazed the found bearing trees:


A larch, 18 ins. diam., bears North, 6.9 ft. dist., mkd. "SW 1/16 S25 BT".

A larch, 16 ins. diam., bears S53°E, 24.3 ft. dist., mkd. "X" "BT".

A 6 ft. steel guard post, North, 3.0 ft. dist. of the monument.

A 6 ft. steel guard post, East, 3.0 ft. dist. of the monument.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Attached Land Survey Monument and Property Boundary decals to the posts.



Cross Index No.