## CERTIFIED CORNER RECORDATION

Corner 1/4 Cor. Secs. 32 & 33 T. 36N R. 27W P.M.M. Lincoln County

1. 1893 original G.L.O. record by Peter McCardell and Abram L. Jaqueth: Set stone and marked two bearing trees.

1969 remonumentation B.L.M. record by Roy G. Leedy: The 1/4 sec. cor. of secs. 32 and 33, monumented with a limestone, 16x10x4 ins., firmly set, mkd. 1/4 on the W. face and witnessed by the remains of the original bearing trees:

A stump hole, bears S82°E, 58 lks. dist.

A stump, bears N75 1/2 W, 35 lkd. dist., mkd. T.

## At the corner point

Set and iron post, 30 ins. long,  $2 \frac{1}{2}$  ins. diam., 24 ins. in the ground with brass cap mkd as shown.

## From which

A fir, 10 ins. diam., bears S39°E, 46 lks. dist., mkd. 1/4 S33 BT. A fir, 12 ins. diam., bears S75°W, 34 lks. dist., mkd. 1/4 S32 BT.

Bury the original stone alongside the iron post and raise a collar of stone, 2 ft. diam., around the iron post.

1999 Certified Corner Recordation by Ronald A. Pearson, MT Reg. No. 9008LS: Found a 2 1/2 ins. diam., iron pipe, 8 ins. out of a mound of stone with 3 1/4 ins. diam., BLM brass cap marked as shown, from which

A fir, 11 ins. diam., bears S39°E 30.3 ft. (46 lks.) dist., healed face.

A fir, 14 ins. diam., bears S75W 22.4 ft. (34 lks,) dist., visible scribe.

No evidence of original bearing trees.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

2. Found 3 1/4 ins. BLM brass monument 8 ins. out of ground surrounded by small mound of stone.

A 13 ins. douglas fir S39°E, 30.30 ft. to aluminum nail, well healed face. A 15 ins. douglas fir S75°W, 22.40 ft. to Aluminum nail, partially healed

face BT visible.

Steel posts 3 ft. North and 3 ft. East, with LSM and boundary decals.

3. Painted mound of stone. Repainted rings and blazes on BT's. All signs are in good shape.

T36N R27W 1/4 S32 S33 1969

corner this sheet

MAGNETIC DECLINATION - 16° EAST

