
CERTIFIED CORNER RECORDATION

Corner 1/4 Sec. 24&25 T. 36N R. 27W P.M., MT Lincoln County

I. <u>1893 G.L.O. Original Record by Peter McCardell et. al.:</u> Set a post, 3 ft. long, 3 ins. square, 24 ins. in the ground, for 1/4 sec. cor. mkd. "1/4 S" on the N. face. Established two bearing trees.

1975 Certified Corner Recordation by D.K. Marquardt No. ES 2989: No record found of the original post and bearing trees. Set by single proportion, a brass cap, mkd. as shown. Established two bearing trees




II. Found a 2 in. diam. iron pipe, firmly set, flush with the ground, no cap attached to pipe.

from which:

A cottonwood, 55 ins. diam., bears N24°E, 41.3 ft. dist., no visible marks. (1975-record-N20°E-39.50 ft.)

III. Accepted position of the found pipe, as per Cerified Corner Recordation by ES 2989, set an aluminum pipe, 30 ins. long, 2 1/2 in. diam., with found pipe inside, 23 ins. in the ground, with a 3 1/4 in. diam. aluminum cap mkd. as shown below.



No other bearing trees available, within limits, as corner falls in a field.

Put a location poster on a railroad tie-fence post, North, 1.0 ft. dist. from monument, to side center.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.

RCNAID A
PFARCON

CERTIFICATION 2006L975

I. Rex O. Rice
Certify the Information shawn hereical and cores

STE

I. Ronald A. Pearson
Certify the Information shawn hereical and cores

STE

I. Ronald A. Pearson
Certify the Information shawn hereical and cores

STE

STE

STE

STE

STE

STE


SIgnature of Surveyor & Seel

Date: 06/11/97

Reg. No.: 9008LS

Employer: U.S. FOREST SERVICE

Office of Clerk and Recorder, County of ______ This "corner record" was filed for record on ______ JULY 31,1997 was noted on the cross-index plat and is assigned page No. 9839, in book No. ______ CORAL M.CUMMINGS, Gould County Official



Cross Index No

R-23

36N

27W P.M., M