INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.


 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner ____S 1/16, Secs. 32 & 33 T. 36 N., R. 27 W., P.M.M. Lincoln . County

- No previous record.
- II. No evidence found.
- III. At the calculated position shown by Certificate of Survey No. 2387 filed at Lincoln County Courthouse, Montana; set a 3/4 in. diam. by 30 ins. long aluminum rod, 28 ins. in the ground, with collar of stone and with 3 1/4 in. diam., U.S.D.A., Forest Service aluminum cap, marked as shown:



from which

A fir, 6 ins. diam., bears $S80^{\circ}E$, 11.1 ft. dist., mkd. S 1/16 S33 BT. A fir, 7 ins. diam., bears $S22^{\circ}W$, 10.9 ft. dist., mkd. S 1/16 S32 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20 East



