
CERTIFIED CORNER RECORDATION

Corner CS 1/16 Sec. 26 T. 36N R. 28W P.M., MT Lincoln County

- I. No previous history.
- II. No history found.
- III. Set by survey, a 3/4 in. diam. x 30 ins. long aluminum rod, 22 ins. in the ground, with a 3 1/4 in. diam. aluminum cap, mkd. as shown, with a "+" for the exact corner point. Built a small collar of stone around the corner monument.




Established two bearing trees and one steel guard post:

A ponderosa pine, 17 ins. diam., bears S31°E, 46.0 ft. dist., scribed "CS1/16 S26 BT".


A fir, 13 ins. diam., bears S82°W, 32.6 ft. dist., scribed "CS1/16 S26 BT".

A 6 ft. steel guard post, bears West, 4.0 ft. distance from the corner monument.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Attached Land Survey Monument and Property Boundary decals to the post.



Magnetic Declination: 20° East



I. Rex O. Rice

certify the information shown herein is true and correct.

I. Ronald A. Pearson

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 4/23/98

Reg. No.: 9008LS

Employer: U.S. FOREST SERVICE

U -19

Sec. 26

Cross Index No.

T.

36N

^{R.} 28W ^{P.M., N}