## CORNER RECORD (Survey of Record Index) See instructions

T 36N R 28W P.M.M. SEC //	COUNTY LINCOLN	, MONTANA
Please check (*) one: Subdivision, Constant, Subdivision, Constant, Book, Subdivision, Subdivision	SUBDIVISION PHASE Page ; Doc. No.	<u>;</u> <u> </u>
Block/Lot/Parcel No(s). LOTS 5 ANO	5 , Corner(s)	·
N77°06'32"E 151.37')	EAGLE	
(Rec. )  A=114°46'30"  R=60.00'  L=120.19'  LOT 6  R=60.00'  L=120.01'	EAGLES NEST DRIVE	
	Found Disturbed N14°57'01"W 12.05'	1
Record Angle Angle LOT 5		
Legend	\	
Stamped ( / Found 1/2" Rebo	Rebar With Plastic Cap Warquardt 7328 S )  ar With Plastic Cap ANDS 7975 S )  In Table 10	20, 22.
	WINTANA.	
"	DAWN MARQUARDT CE 7328 LS 0	
SKETCH: show enough information to clearly identify the corner (us	se back if needed). OVAL confidentions	• Location in Sec
Office of Clerk and Recorder, County of This "Comer Record" (Survey of Record) was filed for record	Brian Carnel represented terem was faithful	ceptify that the work
on, was noted on the Cross Index Plat or listed in the Survey of Record Index and is assigned:	Signature of Ground Par	ny Chief
Page No	10:1	
STATE OF MONTANA LINCOLN COUNTY RECORDED: 01/17/2008 10:00 KOI: CCER'S	Signature of Surveyor	& Seal
TAMMY D. LAUER CLERK AND BECORDER  FEE: \$0.00 BY: Secure Secure of  To: MARQUARDT SURVEYING INC. 201 3RD AVENUE WEST, KALISP	Date: 12-14-07 Lic. No ELL, Hoyer: Marquarett & Marque	
Adopted November 4, 2004, Montana Board of Professional Engineers & Professional Land Surveyors		