


CERTIFIED CORNER RECORDATION

Corner WC NE COR SEC 15 T. 36N R. 28W P.M.M. Lincoln County


1. At the Section corner position from COE [Libby Dam - Lake Koocanusa Cadastral 1972 map], found stone, 3 bearing trees and stump. Set witness corners.
2. Found 4½" x 4½" square concrete monument with 3½ ins. Corps of Engineers brass cap marked as shown, flush with ground.
A 15 ins. Douglas Fir bears S 5°W, 15.80 ft. dist., well healed face.
A steel T post bears North, 1.30 ft. dist., with sign WC.
Corner bears SE, 3.0 ft. dist. from edge of cliff.
3. Cleared brush and exposed and painted the concrete portion of monument.
Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Established:

- A 14" Douglas Fir bears S5°E, 35.70 ft. dist. scribed "WC BT".
- A Steel Post with LSM decal bears South, 3.0 ft. dist.



MAGNETIC DECLINATION - 16° EAST



SKETCH OF CORNER

CERTIFICATION
CURT HECKROTH
 certify the information shown herein is true and correct.
 Signature Ground Party
LAWRENCE A. GLAHE
 certify that the Corner Record Book represents work performed by me or under my supervision in compliance with the "Corner Recordation Act" (No. 12-1401, et seq. M.C.A.)
 9748 LS
 Date: 1-25-10
 Employer: GLAHE & ASSOCIATES, INC.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record 224161 BOOK: CCR CC&R'S PAGE: 11395 Pages: 1
 was noted on the cross-index STATE OF MONTANA LINCOLN COUNTY
 book No. RECORDED: 01/27/2010 3:37 KOI: CC&R'S
 TAMMY D. LAUER CLERK AND RECORDER
 FEE: \$0.00 BY:
 TO: FILED

Cross Index No. J-17 T. 36N R. 28W PMM

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

Sec. 15

● corner this sheet