


CERTIFIED CORNER RECORDATION

Corner COE 3403-1 Sec 11 T. 36N R. 28W P.M.M. Lincoln County


1. Libby Dam - Lake Kookanusa Cadastral 1972 map
2. Found, 3" Corps of Engineers Brass Cap in 4" concrete, stamped as shown.
3. Painted red bands around BTs and attached LSM and BT signs.

Established:

An 8 ins. Douglas Fir bears N53°W, 15.9 ft. distant, scribed "3403-1 BT"
 A 12 ins. Ponderosa Pine bears N4°E, 19.5 ft. distant, scribed "3403-1 BT"
 Steel posts with PB & LSM decals, bear East and South, 2.0 ft. distant.



MAGNETIC DECLINATION - 16° EAST



SKETCH OF CORNER

CERTIFICATION

I, ERICH SCHRACK
 certify the information shown here is true and correct.

I, LAWRENCE A. GLAHE
 certify that this Corner Recordation represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (No. 22-401, et seq. M.C.A.)

Date: 1-25-10 9748 LS
 Employer: GLAHE & ASSOCIATES

Office of Clerk and Recorder, County of Lincoln. This "corner

record" was filed for record on 224173 BOOK: CCR CC&R'S PAGE: 11407 Pages: 1

was noted on the cross-index plc RECORDED: 01/27/2010 3:49 KOI: CC&R'S

book No. TAMMY D. LAUER CLERK AND RECORDER

FEE: \$0.00

BY: [Signature]

TO: FILED

Cross Index No. G 19-20 T. 36N R. 28W PMM

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

Sec. 11

● corner this sheet