INSTRUCTIONS

 Original and/or sur
Description of evid ent record used to evaluate the corner position. ound, note discrepancies in the record, state method of establ corners.

3. Description of monument and accessories set to perpetuate the corner position.

Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fiff in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

23 N-1/16Corner_ T. 36N R. 28W P.M.M. Lincoln County

ĩ. None

- Found 1" pipe with brass disc stamped "E.S. 2989", set by D.K. Marquardt, per Certificate of Survey No. 118.
- III. Drove a 3/4" x-24" rod into ground with 3-1/4" alum. cap for true corner position.

1" pipe with brass disc bears S.32°36'W., 0.39'


Established BT's as follows:

5" fir bears S.57°E., 10.0', scribed N-1/16 S24 BT 6" fir bears N.27°W., 4.7', scribed N-1/16 S23 BT

Posted BT, Attention, and Land Monument signs; painted blazes red; drove steel post in ground along side corner monument.

For monument location, see the Certificate of Survey on file.

> 34" ALLIM. CAP RZOW



	[•
Office of Clerk and Recorder, County of Lincoh	. This "corner	Sec. 23
record" was filed for record on the <u>Wec 27</u>	day of 1925	
was noted on the cross-index plat and is assigned page No32	,	1
book No fant be sugilly & County Office	all brechoff	
Cross ladex No 021	36N 28W	• Corner this shoot