## CERTIFIED CORNER RECORDATION

Corner P.M., MT County

1893 G.L.O. Original Record by Peter McCardell et. al.: Set a post, 3 ft. long, 3 ins. square, 24 ins. in I. the ground, for the standard 1/4 sec. cor. mkd. "SC 1/4 S" on N. face.

Established two bearing trees:

A pine, 40 ins. diam., bears N06°W, 50 lks. dist., mkd. "SC 1/4 S BT".

A pine, 10 ins. diam., bears \$26°30'W, 10 lks. dist., mkd. "SC 1/4 S BT".

1977 & 1981 Certified Corner Recordations by D.K. Marquardt Registration No. 2989 ES: No evidence of corner found, set by single proportion, an iron pipe, 36 ins. long, 2 in. diam., 30 ins. in the ground, with brass cap, mkd. as shown:



Established two new bearing trees:

A pine, 8 ins. diam., bears \$12°E, 29.26 ft. dist. from the corner.

A pine, 6 ins. diam., bears N36°E, 40.11 ft. dist. from the corner.

II. Found a 2 in. diam. iron pipe, with a 2 in. diam. brass cap, firmly set, protruding 3 ins. above the ground, mkd. as shown above. Cap not mkd. with "CC", as stated in Corner Recordation.

from which:

A pine, 10 ins. diam., bears S12°E, 29.3 ft. dist., with visible scribe.


A pine, 8 ins. diam., bears N36°E, 40.1 ft. dist., with visible scribe.

III. Established one new bearing tree:

A pine, 6 ins. diam., bears East, 1.6 ft. dist., with a Land Survey Monument sign attached.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Corner is located South, 12.0 ft. dist. from the centerline of dirt road.

Magnetic Declination: 20° East.



Date: 04/15/97 Reg. No.: 9008LS

SKETCH OF CORNER

Office of Clerk and Recorder,	County of LIN	COLIN This "corner r	record" w	as filed for record
on <b>JULY 31,1997</b>			igned pa	ge No. 9871
in book No	CORAL	M.CUMMINGS	Bu	pels
		County Office	cial /	· -

<u> </u>		
- <del> </del>	- <u>-</u> -	
-		

Employer: U.S. FOREST SERVICE