

## INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

HES 487 COR 3 SEC 7 T36N R31W LINCOLN CO.

FND OLD STONE MON W/"X" CUT  
0.70' ABOVE GRD & 3 HES 487

WRITTEN ON NE SIDE

FND OLD BT 30" LARCH N26°W 28.25' DIST

OLD SIGN READS: S22°41'E 42 LINKS 7/12/78


FND OLD BT 20" LARCH S18°W 32.12' DIST

OLD SIGN READS: N17°30'E 32.0' DIST 7/12/78

SET STEEL POSTS W/DECALS 52-4 & 52-9

1) NORTH 1.20' DIST

2) EAST 0.90' DIST



SKETCH OF CORNER

## CERTIFICATION

I, \_\_\_\_\_  
certify the information shown herein is true and correct.

Signature Ground Party Chief

1. Thomas E. Sands

I certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

Signature of Surveyor & Seal

Date: 7/23/93 Reg. No. 7975-S

Employer: Sands Surveying, Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the July 27, 1993 day of 19, was noted on the cross-index plat and is assigned page No. 5368, in book No. \_\_\_\_\_

Coral M. Cunningham, B.S.  
County Official

Cross Index No. HES 487-3 T. 36N R. 31W PMM

Sec.			

• corner this sheet