

INSTRUCTIONS

1. Original and/or substitute record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.



CERTIFIED CORNER RECORDATION

Corner $\frac{1}{4}$ corner between Sec. 35 & 36 T. 37N R. 27W P.M.M. Lincoln County

Record: Set a sandstone 16x10x6 ins. 11ins. in the ground

Dug pits for RMS.

No evidence found. Set aluminum cap by single proportion.



SKETCH OF CORNER

CERTIFICATION

I certify the information shown herein is true and correct.

Signature Ground Party Chief

D.K. Marquardt

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

D.K. Marquardt

Signature of Surveyor & Seal


Date 7-8-81 Reg. No. 0989ES

Employer:

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the February 17th day of 1982 was noted on the cross-index plat and is assigned page No. 1547, in book No. 1.

Eleanor L. Daugherty Betty L. Concess
County Official Deputy

Sec. 35



Cross Index No. X-21 T. 37N R. 27W PMM

• corner this sheet