CERTIFIED CORNER RECORDATION

Corner E 1/16 Sec. 11 & 2 T. 37N R. 28W P.M.M. Lincoln County

1. <u>1989 Certified Corner Recordation by MT Reg. No. 2734S</u>: Set a standard 3 1/4 inch Forest Service alum. cap on a 5/8 inch rod 28 inches into the ground;

from which:

A 7 inch fir bears S27 $1/2^{\circ}E$, 17.05 feet, scribed E 1/16 S11 BT. An 8 inch fir bears N26°E, 20.30 feet, scribed E 1/16 S2 BT. Set a USDA steel post 3 feet north of corner.

2. Found a 3 1/4 inch USDA aluminum cap 6 ins. out of ground, surrounded by small mound of stone.

Steel post with LSM and Boundary Signs 3 ft. north.


A 10 inch douglas fir N32°E, 20.30 ft. with a well healed face (record N26°E).

A 10 inch douglas fir S23°E, 17.05 ft., with a partially healed face, illegible scribing visible (record S27 1/2°E).

3. Restacked and painted stones around monument.
Put aluminum nails at record distances and repainted blazes and rings on BT's.
Attached new BT tags.



MAGNETIC DECLINATION - 16° EAST



Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet