# CERTIFIED CORNER RECORDATION

Corner C.C. of Sections 2 & 3 T. 37N R. 28W P.M.M. Lincoln County

1. 1894 Original Survey by F. Sizer and A. Jaqueth: Set a quartzite stone 14x10x6 ins., 10 ins. into the ground for closing corner for sections 2 and 3, marked C.C. with B.P. on north and 2 grooves on east and 4 grooves on west faces,

#### from which:

A fir 14 ins. diam. bears S46 45W 37 lks. marked T37N R28W S3 BT.

A tam. 8 ins. diam. bears S51°E 21 lks. marked T37N R28W S2 BT.

1969 Remonumentation BLM: Set an iron post 30 inches long 2 1/2 inches diam., 24 inches into the ground,

## from which:

A larch 7 ins. diam. bears S54 1/2°E 55 lks. marked T37N R28W S2 CC BT.

A fir 6 ins. diam. bears S61°W 54 lks. marked T37N R28W S3 CC BT.

Buried the stone alongside the iron post.

1989 Certified Corner Recordation by H. Gene Warren MT Reg. No. 2734S: Found 2 1/2 inch brass cap on 2 inch pipe 4 inches out of ground,

#### from which:

A 10 inch stump bears S57E 37.00 feet no scribing visible, painted red.

A 13 inch fir bears S54°E 31.30 feet scribe overgrown.

A 34 inch stump bears S50°W 24.75 feet no scribing visible painted red. An 11 inch stump bears S62'W 35.28 feet no scribing visible, painted red.

Maintained BT's with required signs and paint.




### New BTs:

An 11 inch fir bears S17W 33.10 feet scribed T37N R28W S3 CC BT. Set a 6 foot steel post south 18 feet.

- 2. Found a 3 1/4 inch BLM brass cap 4 ins. out of ground surrounded by small scattered mound of stone.
  - A 15 inch douglas fir S54°E 31.30 ft with well healed face and existing nail in side—center. A 14 inch douglas fir S17°W 33.10 ft with well healed face and existing nail in side—center.

  - A steel post 18 ft. south with LSM decal.
- 3. Restacked and repainted stones around monument. Repainted rings and blazes on BT's, signs and tags are in good shape.

## MAGNETIC DECLINATION - 16' EAST



corner this sheet