## CERTIFIED CORNER RECORDATION

C W 1/16 Sec. 11 T. 37N R. 28W P.M.M. <u>Lincoln</u> County

1. 1989 Certified Corner Recordation by H. Gene Warren MT Reg. No. 2734S: Found a 5/8 inch rebar with a 1 inch yellow plastic cap marked K.E.D. 4975S. Removed 5/8 inch rebar and in its place set a standard 3 1/4 inch Forest Service aluminum cap on 5/8 inch rod 26 inch into the ground;


## from which:

A 6 inch fir bears N17°E 20.80 ft. scribed C W 1/16 S11 BT. A 8 inch pine bears N77°W 33.10 ft. scribed C W 1/16 S11 BT. Set a USDA steel post 3 ft. north of corner.

- 2. Found 3 1/4 inch USDA aluminum monument 4 ins. out of ground. An 8 inch douglas fir N17°E 20.80 ft with well healed face. A stump hole N77°W 33.10 ft. A steel post with LSM and Boundary decals 3.60 ft. north of corner.
- 3. Stacked and painted small mound of stones around monument. An 8 inch douglas fir N34°W 19.80 ft. scribed CW 1/16 S11 BT. Put aluminum nail at record distance and repainted ring and blaze on existing BT. Tags are good.




## MAGNETIC DECLINATION - 16° EAST



\_\_. This "corner Office of Clerk and Recorder, County of \_ <u>Lincoln</u> record" was fi 224124 BOOK. CILL
STATE OF MONTANA LINCOLN COUNTY PAGE: 11376 Pages: 1 was noted on RECORDED: 01/27/2010 12:46 KOI: CCGR'S in TAMMY D. LAUER CLERK AND RECORDER book No. \_\_\_FEE: \$0.00 TO: FILED , Cross Index No. <u>G-18</u> T. <u>37N</u> R. <u>28W</u>

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet