| | CERTI | FIED | COR | NER | RECO | RDATIC | N | |
|--------|--------------------|------|-----|-----|------|--------|---------|---------|
| Corner | E. 1/16 Sec. 11•14 | T | 37N | R | 28W | P.M.M | Lincoln | _County |


1. 1983 Certified Corner Recordation by Carl R. McMillen, MT Reg. No. 4659—S: Set aluminum monument 1 ft. below surface of hay field, (5/8"x24" aluminum monument w/3" cap).

from which:

A 12" pine, bears S8"E, 53.30 ft., mkd E1/16 S14 BT, with X cut in tree below BT tag. An 8" pine, bears S46"E, 85.45 ft., mkd. E1/16 S14 BT. Set carsonite post with location tag in fence line, bears S11"W, 40.83 ft.

- 2. Found a 3 1/4 inch aluminum cap 16 ins. below surface, east of a 8x6 inch creosote fence corner post.
 - A 13 inch ponderosa pine S52°E (record S46°E), 85.45 ft. with well healed face.
 - A 15 inch ponderosa pine S8E, 53.30 ft. with well healed face.
- 3. Reburied monument with 4 ft lath sticking above ground with flagging. Put aluminum nails at record distances.

 Repainted rings and blazes and put up new BT tags and steel guard post 3 ft. south with LSM and Boundary decals.



MAGNETIC DECLINATION - 16° EAST

