
Corner C.-N.-S.E.-N.E. 1/256 S14 T. 37N R. 28W P.M.M. Lincoln County


1. 1983 Certified Corner Recordation by Carl R. McMillen, MT Reg. No. 4659-S:
 Set driveable aluminum monument in rock cairn, (5/8"x24" aluminum monument w/3" cap).

from which:

A 7" red fir, bears S11"E, 39.10 ft., mkd C-N-SE-NE 1/256 S14 BT. A 6" pine, bears S73"W, 33.10 ft., mkd. C-N-SE-NE 1/256 S14 BT.

- 2. Found a 3 1/4 inch aluminum cap, surrounded by small mound of stones. A 10 inch douglas fir S11°E 39.10 ft., with well healed face. A 11 inch ponderosa pine S73°W 33.10 ft. with well healed face.
- Restacked and repainted stones around monument.
  Put aluminum nails at record distances, repainted rings and blazes on BT's.
  Put up new BT tags.
  Put steel guard post with LSM and Boundary decals 3 ft. south of monument.





Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet