CERTIFIED CORNER RECORDATION
Corner E. 1/4 Sec. 14 T. 37N R. 28W P.M.M. Lincoln County
 1. 1968 Retracement Survey: Set an iron post 30" long, 2 1/2" dia., 24" in ground with brass cap,
from which: A rotted pine stump bears S56°E., 58 lks. (orig. BT) An 8" pine bears N75 1/2°E, 57 lks. A 5" pine bears N49 1/2°W, 101 lks.
1984 Certified Corner Recordation by Carl R. McMillen, MT Reg. No. 4659—S: Found BLM 2 1/2" IP with brass cap, damaged by road maintenance.
from which: A 13" pine, bears N75 1/2°E, 37.62 ft., mkd 1/4 S13 BT. A 9" pine, bears N49 1/2°W, 66.66 ft., mkd. 1/4 S14 BT.
Set USDA alum. mon. 24" in ground in rock cairn, (2 1/2"x30" alum. mon. w/3" cap). Set 54-3 tag in 13" pine bears N75 1/2"E, 37.62 ft. Set 54-3 tag in 5" fence post bears S86"W, 46.2 ft. Set 54-3 tag in 9" power pole bears South, 72.85 ft.
 Found 3 1/4 inch USDA aluminum monument 6 ins. out of ground, surrounded by small mound of stone. A 16 inch ponderosa pine N75 1/2*E 37.62 ft. with well healed face. A 20 inch ponderosa pine N49 1/2*W 66.66 ft with well healed face. A 9 inch power pole South 72.85 ft. with BT tag. A steel post with LSM and Boundary decals 3 ft. north.
3. Restacked and painted stones around monument. Put aluminum nails at record distances in BT's, repainted rings and blazes and put up new BT tags and LSM signs. BT tag on power pole is good. FOREST STATES STA
MAGNETIC DECLINATION - 16' EAST
Steel Post 3 FT. North Steel Post CERT HECKROTH Certify the information shows and correct.
SKETCH OF CORNER 16" PP LAWRENCE A. GLAHE & ASSociation Considerate well by the grant of the complete well
Office of Clerk and Recorder, County of <u>Lincoln</u> . This "corner
record" wds f 224134 BOOK: CCR CC&R'S PAGE: 11386 Pages: 1 Sec. 14
was noted or RECORDED: 01/27/2010 12:55 KOI: CCGR'S in TAMMY D. LAUER CLERK AND RECORDER
book NoFEE: \$0.00 BY: Arms from
Cross Index No. <u>L-21 T 37N R 28W PMM</u>

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet

:Kin