

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing, or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner

NW 1/16th. Section 9 T 37N R 28W P.M.M. Lincoln

County


I. 1991 Davis Surveying Inc.

I set a 5/8 inch dia. x 24 inch long rebar with Yellow PVC cap Stamped: KED 4975 S. from which;

A larch, 6 1/2 inches BT, bears N 34° E 26.7 feet from the center of the tree. Scribed: NW 1/16th. S9 BT

A larch, 9 inches BT, bears N 75.5° W 14.1 feet from the center of the tree. Scribed: NW 1/16th. S9 BT

Painted a 6 inch wide red band around BTs with BT signs on front and warning signs #54.9 on back.



SKETCH OF CORNER

CERTIFICATION

1. Ken Davis

certify the information shown herein is true and correct.

John Damon, Brian Leisz, Bill

Signature Ground Party Chief

Reichel

I, _____
 certify that this Corner Record correctly represents work performed
 by me or under my direction in compliance with the "Corner
 Recordation Act" (MCA 82-101, et seq., M.C.A.)

Signature of Surveyor & Seal
 Date: 8-23-94 REG. NO. 4975 S

Employer: Davis Surveying, Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner

record" was filed for record on the Aug 23 day of 1994

was noted on the cross-index plat and is assigned page No. 4571, in

book No. _____

Chal M Cummings by Bill Buckley

Sec.

