- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- A. Description of moniment and accessories set to perjectuate the corner position.

 4. Skeich or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner No. 1 H.E.S. No. 505 T. 37 N., R.31 W., P.M.M.Lincoln County

1.} & 2.} Found Original Stone Monument set firmly in place, marked:

 $\tt L$ HES 505 on Northeast face, 2 HES 83L on Southeast face, 3 HES 10L9 on Southwest face and 4 HES 50L on Northwest face from which:

A 22 inch dia. Larch bears S. 62° W., 16.0 feet distant.

A 15 inch dia. Larch bears N. 52° 30' W., 13.0 feet distant.


A 24 inch dia. Larch bears S. 85° E., 31.5 feet distant.

A 14 inch dia Larch bears N. 520 W., 15.5 feet distant.

All Bearing Trees tagged and have healed over faces

Mounds of Stone in all four Quadrants.

Set a 2 1/4 inch dia. X 30 inch long Aluminum Pipe with 3 1/4 inch 3.} dia. Aluminum Cap South, 1.00 foot distant from Corner No. 1, marked as shown below:



5" DIA. N. S. J. HES B.T. HES B.T. HES B.T. HES 505	CERTIFICATION Line Melvin D. Lauteren certify the information shown herein is true and correct.
3. 2 5.85 31.5: - 63 24" DM. 2 5.85 31.5: - 63 24" DM. 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Signature Ground Party Chief I. Melvin D. Lauteren certity that this Corner Record correctly represents work performed by me or under my directly in completine with the Corner Recordation Act" (70-2270) Feb. M.C.A.) Signature of Subdyor & Seal Date: L/28/1984 Reg. No. 4232 S Employer: Kootenai Engineering 1
SKETCH OF CORNER	

bnet Brosingel by Bo is assigned page No. 2663, in book No. County Official r. 37 r.3/ PMN · - corner this sheet