

- Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

- Description of monument and accessories set to perpendite the corner position.

 Sketch or corner, show all permient data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner No. 3 H.E.S. No. 505 T. 37 N., R. 3] W., P.M.MLincoln


- Found Original Stone Monument set firmly in place, marked:

 3 HES 505 on Southwesterly face with "X" on top from which:
 - A 26 inch dia. Larch bears N. 16° E., 47.0 feet distant, with healed over face
 - A 3D inch dia. Larch bears N. 450 W., 59.0 feet distant, with partially healed over face

A mound of Stone bears South

- Reset a fiberglass post with Forest Boundary and Attention Signs L inches North of Corner
 - Set a 2 1/4 inch dia· X 30 inch long Aluminum Pipe with 3 1/4 inch dia· Aluminum Cap S· 27° 22′ U·, 1.00 foot distant from Corner No· 3, marked as shown below:





was filed for record on the 9th day of 19<u>84</u>, was noted on the cross-index plat and Panet BF Siecel by is assigned page No. 2665, in book No. County Official deputy 137 13/ Cross Index No.

- corner this sheet