

CERTIFIED LAND CORNER RECORDATION
(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found stone set firmly in place.
2 HES 837 on East face
4 HES 505 on West face
3 HES 836 on South face
Mound of stone East of corner

12" Stump S 12° E 19 links
Down tree S 63° E 9 links
10" Pine S 60° W 7 links (badly damaged)
12" Pine N 23W 25 links (badly damaged)

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1979


8" Fir S 3° W 56.5' marked 3 HES 836
10" Fir N 12°E 15.8' marked 4 HES 505

Set a fiberglass post with Forest Boundary and Attention signs next to corner.
Painted a 6" red band around trees and placed BT and Attention signs.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 756

Surveyor's Seal



I, Don Hardgrove
certify that the information shown herein is true and correct.


Signature of Ground Party Chief

I, Stephen D Staab
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

5619 S
Registration Number

DIAGRAM OF CORNER:



◆ = Corner recorded on the sheet

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 5th day of March, 1980, was noted on the cross-index plat and is assigned page No. 715, in book No. 1

Deputy County Official

Cross Index No. T. 37N R. 31W Mer.

See 19-24-25