DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found stone set firmly in place, 2 HES 505 on South face.

10 "Lodgepole S 30° 14' E, 7.9', partial scribing visible 10" Lodgepole S 62° 15' E, 7.3', partial scribing visible (chopped out)

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1979

12" Pine S. 70° E, 13.2' marked 2 HES 505 BT

Set a fiberglass post with Forest Boundary and Attention signs next to corner. Painted a 6" red band around trees and placed BT and Attention signs.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 756

STEPHEN D.
STAAB
5619 S

SURVE THE

Surveyor's Seal

I, _____Don Hardgrove ______certify that the information shown herein is true and correct.

Signature of Ground Party Chief

I, Stephen D Staab certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:

2HES 505

HES 505

= Corner recorded on the sheet

5619 S Registration Number

Office of Clerk and Recorder, County of	neals
This "corner record" was filed for record on the 5th day of assigned page No, in book No	March 1980, was noted on the cross-index plat and is County Official Light Delly
	Cross Index No. T. 37N R. 31W Mer.