
CERTIFIED CORNER RECORDATION

Corner E 1/16 Sec. 26&35 T. 37 N R. 31 W P.M., MT Lincoln County

- I. No previous history.
- II. Found 1/2 in. diam. rebar. No record filed in Lincoln County Clerk and Recorder's office.
- III. At the position determined by survey, set a 30 in. long, 3/4 in. diam. alum. rod, 18 ins. in the ground, with a 3 1/4 in. diam. alum. cap mkd. as shown:



Established two bearing trees:

A hemlock, 20 ins. diam., bears N40°E, 30.3 ft. dist., scribed "E 1/16 S26 BT". A hemlock, 12 ins. diam., bears S22°E, 31.3 ft. dist., scribed "E 1/16 S35 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

A rebar, 1/2 in. diam., bears N69°W, 1.5 ft. dist. from monument.

Set 6 ft. steel guard post, East, 4 ft., with Land Survey Monument and Property Boundary decals.

Magnetic Declination: 20° East.

