
CERTIFIED CORNER RECORDATION

Corner 1/4 Sec. 23/26 T. 37N R. 31W P.M., MT Lincoln County

I. 1931 original G.L.O. record by Ranney Y. Lyman: Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with a brass cap mkd:



from which:

A spruce,14 ins. diam., bears North, 33 lks. dist., mkd. "1/4 S23 BT".

A spruce, 8 ins. diam., bears S 8 3/4°W, 32 lks. dist., mkd. "1/4 S26 BT".

II. Found an iron pipe, 1 in. diam, with a brass cap, 2 1/2 ins. diam, broken off and pulled out of the ground. Found the bottom of the pipe when digging the hole to place the new monument.

from which:

A rotten spruce stump, bears North, 21.8 ft. (33 lks.) dist., with "1/4 S23 B" visible.

A rotten, loose piece of spruce, laying south of the corner, with "BT" visible.

A spruce, 14 ins. diam., bears \$ 7°W, 32.0 ft. (48 lks.) dist., mkd. "10' N TO BT \$26". (No record)


III. In the exact position of the found bottom portion of original corner, set a 30 in. long, 2 1/2 in. diam. alum. pipe, 22 ins. in the ground, with a 3 1/4 in. diam. alum. cap, mkd. as shown:



Established I new bearing tree:

A spruce, 22 ins. diam., bears N 60°W, 51.9 ft. dist., mkd. "1/4 S23 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Magnetic Declination: 20° East.



ross Index No. R-19

^{t.} 37N ^{R.} 31W ^{P.M}