LINCOLN COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
AFFIDAVIT OF WASTEWATER TREATMENT AND DISPOSAL SYSTEM COMPLIANCE REVIEW FOR SYSTEM INSTALLED, REPAIRED OR REPLACED WITHOUT A VALID PERMIT

Issue Date: 01/28/2022

Property Owner: Corrigan, David and Kimberly

Mailing Address: [redacted]

Telephone: [redacted]

Name of Person Who Installed System Being Reviewed: Dale Schmitt (under license of Barb Rankema)

Type of System Work Reviewed:

__XX__ New Installation ____ Existing System

____ Repair ____ Replacement ____ Extension ____ Other

Describe: 1,000 gallon septic tank with 500 gallon dosing chamber. Pressure dosed system with 3 laterals @ 85-feet in length each. Effluent filter, cleanouts, 1/8" orifice holes spaced at 5-feet, and ME40 pump as noted on site layout.

Property Description:

Legal: GLEN LAKE HILLS, S27, T36 N, R26 W, Lot 21, ACRES 3.45, PM 6749 IN SEC 28

Address or Location: Evergreen Dr.

Assessment Code: 0000054733

Reviewed Design Components:

Wastewater Flows: 300 gpd (3 bedroom) Sewer Lines: Schedule 40 PVS (2" and 4")

Septic Tank: 1,000 Gallons Effluent Filter: Yes Dosing or Lift Tank: Yes (500 gallon)

Drainfield: 255 Lineal Feet Drainfield Construction: drain/wash rock Hydraulic Function: yes

Comments:

System Review Documentation Statement:

I, _____, have inspected/reviewed the components of this system as listed above and found it to be in compliance with the sizing, construction, orientation and operating requirements of Chapter 17, Subchapter 9 A.R.M., Circular DEQ-4 and Lincoln County Wastewater Regulation #3.


Signed: _____ *Date:* _____

Title: _____

NOTICE: This document is not a permit for installation, repair or alterations of a wastewater treatment system. It is merely a statement of affirmation that the Department has conducted an on-site review of an otherwise illegal system and found it to be in compliance with all applicable requirements for that system. This affidavit effectively removes the illegal installation status on this system.

DISCLAIMER

This affidavit of review is not a guarantee by the Department that the system will continue to function properly for any prescribed period of time.


Clean out
power
Well
sch 40-4"
1000-500
Pump
telephone
filter
sch
40-2"
3-85' / 50'
1 1/2 1/8 every 5'
Reserve
power