LINCOLN COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
AFFIDAVIT OF WASTEWATER TREATMENT AND DISPOSAL SYSTEM COMPLIANCE REVIEW FOR SYSTEM INSTALLED, REPAIRED OR REPLACED WITHOUT A VALID PERMIT

Issue Date: 10/21/2020

Property Owner: Terry & Minnie Boothman

Mailing Address: [redacted]

Telephone: [redacted] (Home) (Work)

Name of Person Who Installed System Being Reviewed: Chuck Riley

Type of System Work Reviewed:

___ New Installation __XX__ Existing System

____ Repair ____ Replacement ____ Extension ____ Other

Describe: Three 16' long rockless chambers w/ D box add 42' per lateral and 500 gal tank.

Property Description:

Legal: S01, T29 N, R31 W, ACRES 7.746, TRS 1D1 & 1D2 IN NESW

Address or Location: 50 Billy Bobs Way Libby, MT 59923

Reviewed Design Components:

Wastewater Flows: 375/day Sewer Lines: SCHED 40 Septic Tank: 1500 Gallons EffluentFilter: YES

Dosing or Lift Tank: NO Drainfield: 168 Lineal Feet Drainfield Construction: Chambers

Hydraulic Function: yes

Comments:

System Review Documentation Statement:

I, J. MEYERS RS *have inspected/reviewed the components of this system as listed above and found it to be in compliance with the sizing, construction, orientation and operating requirements of Chapter 17, Subchapter 9 A.R.M., Circular DEQ-4 and Lincoln County Wastewater Regulation #3.*


Signed: _____ *Date:* 10/21/2020

Title: County Sanitarian + Planner

NOTICE: This document is not a permit for installation, repair or alterations of a wastewater treatment system. It is merely a statement of affirmation that the Department has conducted an on-site review of an otherwise illegal system and found it to be in compliance with all applicable requirements for that system. This affidavit effectively removes the illegal installation status on this system.

DISCLAIMER

This affidavit of review is not a guarantee by the Department that the system will continue to function properly for any prescribed period of time.


Moms house
Well
well over 100' away
N
2 Bed
1 Bed
No water inside
No Electricity inside
1500 gal
Soil rocky sandy
perc 3
55'
- slope → 1%
3' deep
0-Ref
16' = 48', needs 48' per bed room
10'
8'
bigger drain field