LINCOLN COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
AFFIDAVIT OF WASTEWATER TREATMENT AND DISPOSAL SYSTEM COMPLIANCE REVIEW FOR SYSTEM INSTALLED, REPAIRED OR REPLACED WITHOUT A VALID PERMIT

Issue Date: 03/17/2021 -2022

Property Owner: Marc & Debbie Zahner

Mailing Address: [redacted]

Telephone: [redacted] (Home) (Work)

Name of Person Who Installed System Being Reviewed: DC ORR

Type of System Work Reviewed:

___ New Installation __XX__ Existing System

____ Repair ____ Replacement ____ Extension ____ Other

Describe: Three lines 54' perf pipe with wash rock.

Property Description:

Legal: ANGEL ISLAND, S29, T29 N, R33 W, BLOCK 001, Lot 70, CS 4095

Address or Location: LOT 70

Reviewed Design Components:

Wastewater Flows: 162/day Sewer Lines: Septic Tank: 1000 Gallons EffluentFilter:

Dosing or Lift Tank: NO Drainfield: 162 Lineal Feet Drainfield Construction: drain/wash rock

Hydraulic Function: yes

Comments:

System Review Documentation Statement:

I, Thomas J Cole, have inspected/reviewed the components of this system as listed above and found it to be in compliance with the sizing, construction, orientation and operating requirements of Chapter 17, Subchapter 9 A.R.M., Circular DEQ-4 and Lincoln County Wastewater Regulation #3.


Signed: Thomas J Cole *Date:* 3-20-21

Title: owner operato

NOTICE: This document is not a permit for installation, repair or alterations of a wastewater treatment system. It is merely a statement of affirmation that the Department has conducted an on-site review of an otherwise illegal system and found it to be in compliance with all applicable requirements for that system. This affidavit effectively removes the illegal installation status on this system.

DISCLAIMER

This affidavit of review is not a guarantee by the Department that the system will continue to function properly for any prescribed period of time.



100' set back from water

lake / Water