LINCOLN COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
AFFIDAVIT OF WASTEWATER TREATMENT AND DISPOSAL SYSTEM COMPLIANCE REVIEW FOR SYSTEM INSTALLED, REPAIRED OR REPLACED WITHOUT A VALID PERMIT

Issue Date: 07/29/2020

Property Owner: Hazel Ivy

Mailing Address: [redacted]

Telephone: [redacted] (Home) (Work) [redacted]

Name of Person Who Installed System Being Reviewed:

Type of System Work Reviewed:

___ New Installation __XX__ Existing System

____ Repair ____ Replacement ____ Extension ____ Other

Describe: Four 80' Laterals in 3' wide trenches.

Property Description:

Legal: DICKEY LAKE LOTS, S16, T34 N, R25 W, ACRES 0.77, LOT 11 OR PRCL A CS 2934

Address or Location: Lot 11

Reviewed Design Components:

Wastewater Flows: 375 g Sewer Lines: Septic Tank: 1500g Effluent Filter: yes

Dosing or Lift Tank: 500 g Drainfield Size: 960 sq ft Drainfield Construction: p dosed chambers

Hydraulic Function: yes

Comments:

System Review Documentation Statement:

I, David w Ivy, have inspected/reviewed the components of this system as listed above and found it to be in compliance with the sizing, construction, orientation and operating requirements of Chapter 17, Subchapter 9 A.R.M., Circular DEQ-4 and Lincoln County Wastewater Regulation #3.

Signed: David w Ivy *Date:* 8-4-20


Title: owner

NOTICE: This document is not a permit for installation, repair or alterations of a wastewater treatment system. It is merely a statement of affirmation that the Department has conducted an on-site review of an otherwise illegal system and found it to be in compliance with all applicable requirements for that system. This affidavit effectively removes the illegal installation status on this system.

DISCLAIMER

This affidavit of review is not a guarantee by the Department that the system will continue to function properly for any prescribed period of time.

LOT LAYOUT


4 -80' laterals
Garage with 1-Bedroom apt
Driveway
500 Gallon pump chamber
1000 Gallon septic tank
2 Bedroom house
Dickey lake