LINCOLN COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
AFFIDAVIT OF WASTEWATER TREATMENT AND DISPOSAL SYSTEM COMPLIANCE REVIEW FOR SYSTEM INSTALLED, REPAIRED OR REPLACED WITHOUT A VALID PERMIT

Issue Date: 6/14/2018

Property Owner: Pat Miller

Mailing Address: [redacted]

Telephone: (Home) [redacted] (Work)

Name of Person Who Installed System Being Reviewed: David Hull for Mick Nelson

Type of System Work Reviewed:

xx New Installation ____ Existing System

____ Repair ____ Replacement ____ Extension ____ Other

Describe: Three 75' laterals using drain rock and perf pipe.

Property Description:

Legal: S19 T35 R27

Address or Location: 801 Bear Trap Road Tract 2 CS 4498

Reviewed Design Components:

Wastewater Flows: 225 gal/day Sewer Lines: 3*75' Septic Tank: 1000 Effluent Filter: Yes

Dosing or Lift Tank: N/A Drainfield Size: 225 Drainfield Construction: Drainrock/PP

Hydraulic Function: Yes

Comments:

System Review Documentation Statement:

I, David Hull, have inspected/reviewed the components of this system as listed above and found it to be in compliance with the sizing, construction, orientation and operating requirements of Chapter 17, Subchapter 9 A.R.M., Circular DEQ-4 and Lincoln County Wastewater Regulation #3.

Signed: [signature] *Date:* 6-18-2018

Title: _____

NOTICE: This document is not a permit for installation, repair or alterations of a wastewater treatment system. It is merely a statement of affirmation that the Department has conducted an on-site review of an otherwise illegal system and found it to be in compliance with all applicable requirements for that system. This affidavit effectively removes the illegal installation status on this system.

DISCLAIMER

This affidavit of review is not a guarantee by the Department that the system will continue to function properly for any prescribed period of time.

Mark / Pat Miller
801 Bear Trap Rd
Rexford, MT 59930

